

ENGINEERING CHANGE NOTICE

DART AEROSPACE LTD

Date: 18.09.06	Job No.: OV18-13	ADR Yes/No: Y	ADR Date: 18.09.06	ECN #: 18- 797
Product No.: D208-667		Created By: CP	Approved By:	
Product Name: Crosstube Installations		Checked By:		

Reason for Change:
CAR 18-221

Documents Released:
 - D208-667-141 Rev. D
 - D208-667-143 Rev. D
 - D208-667-147 Rev. B
 - D208-667-243 Rev. D
 - D208-667-247 Rev. B
 - D407-667-146 Rev. D

IF APPLICABLE: NCR: _____ PAR: _____ CAR: 18-221 CIR: _____ URF: _____

PAPERWORK UPDATE ☐ PARTS MUST COMPLY ☐ PREVIOUS PARTS SATISFACTORY ☒

#	Quality Assurance / Customer Support Actions	Reqd	Resp	Notes	Complete
1	Notify Previous Customers	N			
2	Notify Airbus	N			
3	Notify Leonardo	N			
4	Manufacturing Licensing Agreement Update	N			

#	Engineering Actions	Reqd	Resp	Notes	Complete
5	Required Documents/Drawings/Item IDs Under Review (URF)	N			
6	Update Master Document List (MDL)	Y	CP	MDL-D208-667 Rev. 6	
7	Update Document Record (DR)	N			
8	Update Product Compatibility Matrix	N			
9	Notify TC / FAA of Change (eg. ICA, 8110-3)	N			
10					

#	Document Control Actions	Reqd	Resp	Notes	Complete
11	Move / Update Electronic Files / Design Journal	Y	MG		20.8.18.09.10
12	Update Product Specification Files (Bluefiles)	N			
13	Update Approved/Preliminary Dwg PDF Files	Y	MG		18.09.06
14	Update Product Development Summary (STC applications)	N			
15	Update QSI 021 (TC/FAA STC) and/or STC Approval List	N			
16	Create/Update Parts / STC Database	N			
17	Update / Verify Authorized Release Certificate Database	N			
18	Create / Update Change Record Form / Item Card Database	N			
19	Create / Update Packaging Process Plan (PPP)	N			
20	Red Decals required on Packaging Process Plan (PPP)?	N			
21	Update Controlled Supplier Documents (Cpuls) Database	N			
22	Update Gray Project Binder / Electronic Project Folder	Y	MG		20.8.18.09.10
23	Update D-Part / M-Drawing / DSI / DEO Master Binders	Y	MG		20.8.18.09.10
24	Update "Royalty Paid to" attribute (Parts sold under Dart USA STC's)	N			
25					

Description / Action:

Dwgs updated to correct pictorial error that resulting in misassembled crosstubes. There is no design change associated with this update.

n/A
w 18.11.06

ECN Verified & Complete: _____ Date: _____